

# ENGINEERING - FABRICATION

## REQUIREMENTS / PPE

- Long sleeve cotton shirt (Workwear)
- Long leg cotton pants (Workwear)
- Protective Eye wear safety Glasses – Clear only
- Safety Steel-capped boots must be worn at all times
- Welding helmet (It is recommended you attend with your own due to hygiene reasons)
- Welding gloves (Gauntlets) – **Must be worn in hot works areas at all times**
  - TIG Gloves – **Must be worn for TIG welding only**
  - Riggers Gloves – **May be used for marking out**
- Earphone/headphones (wired)

## STATIONERY

- Lever arch folder / A3 folder
- Notebook
- Pens (red, blue, and black)

## EQUIPMENT

- 45 degree set square
- 30/60 degree set square
- H Pencil
- 2H Pencil
- Eraser
- Steel rule
- Pencil sharpener
- Drawing compass with extension arm
- Scientific calculator

## CAMPUSES

Please make sure you review the relevant campus map before you arrive on your first day.

## NAVAL BASE

<https://www.southmetrotafe.wa.edu.au/sites/default/files/uploads/documents/Campuses/map/NavalBaseMap.pdf>



## THORN LIE

<https://www.southmetrotafe.wa.edu.au/sites/default/files/uploads/documents/Campuses/map/Thornlie%20Campus%20Map.pdf>